



## ROCKFORD FIRE DEPARTMENT INCIDENT UPDATE

### Incident Information:

**Business Name:** Hampton Inn  
**Address of Incident:** 615 Clark Drive  
**Date of Incident:** November 10, 2013  
**Time of Incident:** 06:42  
**Type of Incident:** Commercial Structure Fire  
**Cause of Fire:** Undetermined  
**Estimated Loss:** \$15,000.00

---

### Injury Data:

**Civilian Injuries:** 0  
**Civilian Deaths:** 0

---

### Fire Department Response:

<b>Engine(s):</b>	3	<b>Ladder(s):</b>	1	<b>District Chief(s):</b>	2
<b>Quint(s):</b>	1	<b>Ambulance(s):</b>	1	<b>Haz Mat Unit(s):</b>	0
<b>Boat(s):</b>	0	<b>Diver(s):</b>	0	<b>Other(s):</b>	1
<b>Total Firefighters:</b>	24				
<b>Response Time:</b>	6 min				

---

### Narrative:

The Rockford Fire Department was dispatched to the address listed above for an electrical fire in a hotel. The first arriving apparatus, Quint 5, found the hotel evaluated. Quint 5 located an extinguished fire in an office area with a sprinkler head off and smoke on the first floor. The sprinkler system had extinguished the fire. The Fire Department cleared smoke from the building and allowed guests to return to their rooms. An Investigator was called to investigate the cause of the fire. The cause is still under investigation. The damage is estimated at \$15,000. There were no injuries.

---

**For additional information contact:** 987-5660

**Prepared by:** Acting District 2 Ken Eitenmiller on 11/10/13 at 18:30

, on 11/12/13 at 11:21